COLD GAL

Size 370g NET

Cold Galvanising Spray Paint

- Protects Iron and Steel against Rust and Corrosion
 - · Zinc Rich
- Provides Excellent Long-Term Protection 370g NET

Impact-A Cold Gal is a zinc rich Weld Through coating that provides long term protection against rust and corrosion.

The unique action of Impact-A Cold Gal reacts with the metal to replace damaged surfaces and produce a protective barrier. Impact-A Cold Gal protects iron and steel against rust and corrosion. It is ideal for steel roofs, fences, gates or wrought iron, boats and marine equipment, air conditioning and heating systems.

Impact-A Cold Gal provides excellent long-term protection and is ideally suited

to coat any metal parts that require protection or touch ups to anygalvanised parts..

Surface Protection

The correct surface preparartion is critical. Both the paint and the metal must be in contact if a successful reaction is to take place. Wire bushing or mechanical sander must remove all loose materials until a firm base is established. The surface must be thoroughly cleaned and free from grease, oil, dirt, and other contaminants. DO NOT use a Rust Converter.

Before Spraying

surface must be thoroughly cleaned and free from grease, oil, dirt, and other contaminants. DO NOT use a Rust Converter. Before Spraying Cover nearby areas to

Spray Application

Adjust nozzle to the desired spray pattern. The horizontal setting used when spraying up and down. The vertical position when spraying across. Hold the can upright approximately 25cm from the surface. It is better to apply several light coats rather than one heavy coat.

Drying Time

Dries to touch in 30 minutes. Apply additional costs if required after 8 hours.

After Spraying

To clean nozzle and prevent blocking, turn the can upside down and press button until only gas escapes.

Over Coating

Impact-A Cold Gal does require a topcoat. Where a topcoat is desired the surface maybe be over coated with both Enamel and Acrylic paint systems.

Clean Up

Use mineral turps to remove any overspray.

Caution – Highly Flammable

Keep away from flame and heat. Keep in a cool place out of the sun. Do not puncture or incinerate can even when empty. Do not store above 50°C. Avoid breathing vapours or contact with skin or eyes.

Code: 10140



